
Damage/wear/hole

Front View Rear View 57 Loose/broken/delaminated Previous repair Missing Add-ons


Spindles not original to desk

Inscriptions

Right Side




Left Side



■ Inscriptions

Spindles not original to desk

Top



Loose/broken/delaminated

Damage/wear/hole

Previous repair

Replaced piece

Missing


Spindles not original to desk


Add-ons

■ Inscriptions

Bottom

Bottom





- Loose/broken/delaminated
- Previous repair

Missing


Add-ons


Damage/wear/hole

- Spindles not original to desk
- Inscriptions

Drawer Front, Outer Surface

Rear Surface of Drawer Front







- Loose/broken/delaminated
 Damage/wear/hole
- Previous repair
- Replaced piece

- Missing
- Spindles not original to desk
- Add-ons
- Inscriptions

Inside Surface of Left Drawer Side

Inside Surface of Right Drawer Side






- Loose/broken/delaminated
- Damage/wear/hole


- Previous repair
- Replaced piece

- Missing
- Spindles not original to desk
- Add-ons
- Inscriptions

Rear Surface of Drawer Back

Front Suri ice of Drawer Back





- Loose/broken/delaminated
- Previous repair

Missing

Add-ons

Damage/wear/hole


- Spindles not original to desk
- Inscriptions

Upper Surface of Draw r Bottom

Damage/wear/hole

Lower Surface of Drawer Bottom


Inscriptions




Spindles not original to desk

Outside Surface, Right Drawer Side

Outside Surface, Left Drawer Side





Loose/broken/delaminated

Previous repair

Missing

Add-ons

■ Damage/wear/hole

■ Replaced piece

Spindles not original to desk

■ Inscriptions